SECTION OR SUBDIVISION		Corner No. 24/
TWP. / N , RANGE 10 4 11 E	00101	CORNER DESCRIPTION
S Este	B.T 18" DW. fir Mhd.	Rochs + 3x3 x24 stake fd. by V.BE May, 1945
¥ → 1160 € ←	TIN RIIE - 531	x - indicates position of sec. cor marker
W. F.	BT	or see cor marker
Long		
W.O. REF.		
		Card. of

HOOD RIVER COUNTY CORNER RESTORATION FORM		Condition Report Only		
Section: 31 Township: 1N Ra		Date: 5/30/24	Not Found x Renewed	
Section: 31 Township: 1N Ra	inge: ++L	· ·	Unrecorded	
Corner Designation Z25			Surveyed In	
•			Referenced Out	
Previous Renewals/Surveys, etc: (1859)The U.S. General Land Officontract No. 79, to survey the Basoutheast corner of T1N R32E, corner to Township 1 North of Ra-18" fir, N30W, 35 links -18" fir, N84E, 3.33 links (1879) The U.S. General Land Offication of Samuel Land Offication of Samuel Land In Samuel Land	ce contracted with Day seline from the souther souther anges 10 & 11 East." Refice contracted with Aley the exterior lines of found: g. Set references: fice contracted with Headivide T1N R10E, conducted by the out of specifications.	east corner of section 329 through June 8, 1859. eferences set: onzo Gesner, Deputy Sur T1N R10E. Gesner foun delarum, Deputy Sur Jucted in November of 2 jons and therefore resur	y Surveyor, under In T1N R8E to the Thompson set "post for rveyor, under contract No. d old post rotted down Surveyor, under contract 1882. Meldrum found rveyed the Baseline. Found	
6 notches on North, East and Wo-8" fir, N29E, 38 links, marked " -3" fir, N62W, 18 links, marked (1945)Corner found by V.B.E, US References found: -22" D. fir (overgrown), N14W, -18" W. fir, N60E, 30', marked (1984) Danny Cron, under control of 1984. Cron set 2"x30" alw	est faces. References for the state of the s	ound: · Card No. 241, as "rocks t Service, CS1985036, pouninum cap stamped "T	e and 3"x3"x24" stake" erformed field work in the F1N R10E S36/R11E S31/S2	
T1SR10E 1984 PLS1028" Set ora -12" D. Fir, N46E, 26.3', scribed -19"D. Fir, N57W, 38.2', scribed Set Bearing Tree and Attention s	ange post with sign atta "T1NR11ES31BT" "T1NR10FS36BT"	ached warning against c	lestroying. Set references.	
on bottom of blaze.				
Monuments & Accessories Four (2024) S. Deshong of US Forest S References found: -27" Doug fir, N57W, 38.2' with -13" doug fir, N46E, 26.3' with	Service, Columbia Land healed blaze	irce) Zone recovered corner	monument as set in 1984.	
Monument Detail Found 3" Aluminum Cap on 2.5 stone.			T1N R10E R11E S36 S31	
Monument Set (Procedures and None	d Description)		T1S R10E 1984	
New Accessories: None		Survey	vor's Seal	
Location & Comments:	Compass Declination Firm/Agency USDA For		, <u>or</u>	
-Corner lies approximately 100' South of Rd170	Gifford Pinchot National Forest, Col	umbia Lands Zone	REGISTERED PROFESSIONAL	
-Set aluminum guard posts 5'	Address 987 McCle		LAND SURVEYOR	
East and West of monument w/Property Boundary and	Vancouver,	WA 98661 shong	Simle	
Land Survey Monument signs	rarry cines		OREGON MAY 16, 2015	
attached.	Notes R. Ellis, C. C		ERIELLE F. LAMB 89906	
-Painted 6" red bands around Bearing Trees.	44 ICHE22 2		EXPIRES: 12/31/2024	