PLAT OF
PARTITION OF THE LANDS BELONGING TO
HEIRS OF W. W. FOSS, DECEASED

In the S.W. 1/4 of Section 31, T. 3 N.—R. 11 E. W.M.
Wasco County, Oregon.
Scale 1" = 3 chains - Sept. 26, 1907.

John Leland Henderson
Surveyor.



COPY OCT. 30TH. 1908, by P.M.H.L.

M.H.

13

0840 # 2-374

102