11-107

SEC. 7, T.IN., R.10E.

SEC. 18, T.IN., R.10E.

SEC. 19, T.IN., R.10E.

SEC. 30, T.IN., R.10E.

LOST LAKE ROAD

N.W. cor. sec.

Bench Mark

Tree

819.23 S.24°55'E.

366.15 S.24°55'W.

478.99 S.19°22'E.

779.07 S.01°48'E.

916.24 S.02°01'E.

334.20 S.06°22'45"W.

407.67 S.31°45'45"W.

1029.07 S.05°18'15"W.

706.05 S.10°13'30"W.

S.05°01'W. 513.60

1623.23 N.89°40'30"E.

5295.94 S.00°30'07"E.

SEC. COR. found - B.C. in N.C. as of record

1618.28 S.12°54'45"W.

1630.92 S.09°22'E.

SEC. COR. found - I.P. as of record

2641.63 S.00°58'56"E.

1/4. COR. found - I.P. as of record

2669.51 S.01°44'59"E.

SEC. COR. found - I.P. as of record

1275 S.01°44'59"E.

SEC. 25, T.IN., R.9E.

SEC. 12, T.IN., R.9E.

SEC. 13, T.IN., R.9E.

SEC. 24, T.IN., R.9E.

1038.44 N.11°43'12"W.

2336.41 S.23°36'W.

973.01 S.19°53'30"W.

360.69 S.00°04'E.

571.01 S.41°35'W.

417.49 S.24°36'30"W.

1216.80 S.32°28'W.

588.87 S.23°13'W.

514.77 S.11°42'W.

613.00 S.05°38'30"W.

S.25°04'30"W. 440.21

543.18 S.01°48'45"E.

772.78 S.02°13'15"E.

1858.67 S.01°58'05"W.

604.67 S.03°00'45"E.

S.87°W. 58

2242.25 S.88°19'01"W.

313.35 S.65°45'15"E.

427.48 S.69°30'45"W.

306.77 N.75°58'25"W.

447.17 S.22°58'15"W.

1345.77 S.04°45'E.

1463 S.72°42'W.

1358.87 N.18°17'45"E.

Average existing ℄ of Main Tony Creek Road & approximate location of Tony Creek Water Supply Main

TONY CREEK Water Supply Intake Area

assumed basis of bearing

scale — 1" = 600'

REGISTERED PROFESSIONAL LAND SURVEYOR

Danny E. Cron

OREGON AUGUST 22, 1975 DANNY L. CRON 1028

April 18, 1978

"SURVEY"

FOR — Champion Timberlands

LOCATION — Sec. 13, 24, 25, T.1N., R.9E., Sec. 7 & 18, T.1N., R.10E., W.M. HOOD RIVER COUNTY, OREGON

FILED

MAY 19 1978

COUNTY SURVEYOR

By

DEPUTY

11-107 #78051