

SECTION OR SUBDIVISION


$\frac{116}{127}$

CORNER No.

31

TWP. 18, RANGE 9 & 10 E, W.M.

CORNER DESCRIPTION



Corner to be reestablished

destroyed by Road

Construction

$\frac{116}{127}$ T15 R10E
T15 R9E

W.O. REF.

CARD

1

OF

3

SECTION OR SUBDIVISION

$\frac{116}{127}$


CORNER No.

31

TWP. 15, RANGE. 9410 E, W.M.

CORNER DESCRIPTION

Re-establish
Destroyed by Road
Constr.



W.O. REF. _____

CARD

2

OF

3

SECTION OR SUBDIVISION

$\frac{116}{127}$

TWP. 15....., RANGE 9^E 10^E....., W.M.

CORNER No.

31.....

CORNER DESCRIPTION

FD 2" Axle

IN MOUND OF

Rock. 8' south
of Rd ϕ .

FD old Stump

Flush with Ground
which fits close
to GLO ties, it
Bears N. 58° E 112'
from Axle

Act March 1977

CARD 3..... OF 3.....

W.O. REF

I accepted to
axle as best available
evidence for corner