Section or Subdivision $33/34$	Corner No. 495
TWP. 3N, RANGE O. E, W.M.  R.P. GCREW IN 10" OAK I'M OF STEEL FC	CORNER DESCRIPTION  1/4 COR 33/34  2" STEEL AXLE ON
33 34 14 COR	& OF PAVE
W.O. REF. <u>TENNESON</u> #4175	CARD OF 3

SECTION OR SUBDIVISION	33 34	CORNER No. 495
TWP. 3 M, RANGE 10	<u>E</u> , W.M.	CORNER DESCRIPTION
NAIL	CA TOWER FOLE	CORNER IS AN BRASS
TO THE WOOD	N/TAS	SOUTH OF & OF POST
O NX AC	6	CANVENT,
I ROST V	CANYON	@= FO. 76" I.R. WITH
Bules But sul		RED PLASTE CAP STAMPED
1 TAS 6 66 NO		KLEIN 9 ASS. LIS. 982 MORTH 20.00'
NATE & SHAMER		(B)= FD. AKLE N. 34°E
W.O. REF. DATE: 3-2	3-84	27.75'
		2 2
	44.444	CARD OF 3

Section or Subdivision /	4 33 34	Corner No. 499
TWP. 3N, RANGE 10	2, <b>W.M.</b>	Corner Description
14"OAK 33 XX	8, POLE WITH 10	9-90 ED: STONIE /IR (SEE PACE of CARD) AS BED JLH.
Jumo of Styles o	Est Campon for  O DLO BC I'M MODE CASE (NOT DUG UP- USEDEOR RP)	ENEURIS; LEFT ELD 13C AS RP. & POSSIBLIZ DEED CONVER
W.O. Ref	90	CARD 3 OF 3

1. 1 1

While going through the JLH books, notes were found pertaining to the Quarter Corner to Sections 33 & 34 of 2N 10. References to various iron pipes and plow shares were checked and searched in the field. A gas pipe East of the corner was found; at a point 476' West of the gas pipe we dug 12" below the surface and found a large stone with a 3/8" iron rod driven alongside to be plus or minus 0.3', and on line with the Center of S.34, as called by J.L.H. A strong reading was found 600' East of the corner, where J.L.H. called a plow share, but not dug out; 330' West of the corner fell in a swale that has been filled and culverted -- no pipe found.

BARK - 5 495 3 of 3

	7.76
Section or Subdivision 33-34	Corner No. 547
TWP. 3 N, RANGE 10 F, W.M.	Corner Description 2" Steel Axle
W. of steel fo	on E of Pave.
Togen Tel. P.	;
33 2 34	
1/4 cor.	
Ŧ	
W.O. Ref. 4175 Krumbah	