
TWP. 2 H., RANGE 10 E, W.M.	Common December
TWP, RANGE	CORNER DESCRIPTION
PANER POLE D W.O. REF.	VA CORPER BETWEEN SEC 26 2 25 FD. 2" IRON PIPE ON FACT EDGE OF ICAGATION PITCH ZI DEC. 1971 CARD OF 2

SECTION OR SUBDIVISION	CORNER No. 550
TWP. 2N, RANGE O, E, W.M.	CORNER DESCRIPTION
	4 CORNER BETWEEN
	JEC 26 \$ 25. CORNER
	IS A 2" IP IN THE
SEE BACK SIDE	CENTER OF THE IR-
	RIGATION DITCH,
	2 REF. MON, SET. BOTH
	RP'S ARE 22" BRASS
	CAPS EPOXY GLUED IN
	CONCRETE, NORTHERLY RP
W.O. Ref	IS SET IN CONC. ENTRANCE
	TO STADLEMAN BLDG. RP#2 IS ON THE EAST EDGE OF CIRC
	CARD OF CONCRETE APRON OF MAN HOLE NEAR PROPANE TANK, SEE DRAWING ON BACK.



HOOD RIVER COUNTY CORNER RESTORATION FORM

SECTION 26, TOWNSHIP 2 NORTH RANGE 10 EAST, W.M.

DATE: MAY 27, 2014

CORNER DESIGNATION: EAST QUARTER CORNER

PREVIOUS RENEWAL: CORNER CARD NO. 550

MONUMENT FOUND: FOUND I 1/2" IRON PIPE AT SE'LY EDGE OF CREEK/DITCH.

0.4' BENEATH BED OF CREEK.

ACCESSORY FOUND: FOUND STEM OF CORNER CARD NO. 550 RP #I BRASS CAP

CAP IS MISSING.

FOUND STEM IN CONCRETE RAMP TO STADELMAN FRUIT BUILDING.

NEW ACCESSORY:

SET 2 1/2" BRASS CAP IN RECENTLY CONSTRUCTED 6 FOOT DIAMETER

CONCRETE VAULT LID AT ODELL SANITARY DISTRICT LIFT STATION.

SET BRASS CAP WAS RECOVERED AT TIME OF DEMOLITION OF AN EXISTING CONCRETE VAULT AND RESET IN THE NEW VAULT AT A DIFFERENT POSITION.

PREVIOUS DESIGNATION FOR CAP WAS CORNER CARD NO. 550 RP #2.

WYEAST SURVEYS
KEVIN DOWD
4399 WOODWORTH DRIVE
MT HOOD-PARKDALE OR 97041

HEGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
KEVIN DOWD
2393

RENEW: MAY 29,2015

