


SECTION OR SUBDIVISION

33 34

TWP. 1N, RANGE 10E, W.M.CORNER No. 733

CORNER DESCRIPTION

Sec. Cor.I. pipe 2" x 12"fd. by V.B.E. Mar., 1946

B.T. - 8" maple stump

B.T. 10" Oak snag
(down)mhd. - R
B.T.

W.O. REF. _____

CARD 1 OF 2

SECTION OR SUBDIVISION 34 $\frac{33}{4}$ 34

CORNER No. 733

TWP. 1N., RANGE 9E, W.M.

CORNER DESCRIPTION

Sk Cor Sec 34

ED 1/2" T.P.

Bearing Tree

in NE. Quadrant

fd down. Tree is

a 20" Buckskin Fir

log scribes still

visible. No other

trees fd.

10/25/76 ack

CARD OVER →

N 37° E
47'
1/2" IP
WRONG
10/11/84
W.O. REF. 1944
D.L. survey
for
USFS

- Found = 1) Stamp of 20" D.F. with axe marks - S. 22° E. - 9.9'
- 2) Uprooted 18" W.F. with scribing visible - N. 23° E. - 40.26'
- 3) Stamp of 22" D.F. - N. 36° W. - 67.98'
- 4) Bent 1 1/2" I.P. - N. 70° W. - 1.25'
- 5) 1/2" I.P. - N. 80° 06' 20" W. - 10.75'



- Set = 1) Set 3" Aluminum Cap stamped
- 2) 5" D.F. - N. 28° E. - 35.8' - scribed "TIN R9E 334 SCBT"
- 3) 6" Noble - N. 30° W. - 26.4' - scribed "TIN R9E 333 SCBT"

↑
From DLC Survey
1983

733

996715
9967.16