


SECTION OR SUBDIVISION CW 1/16 24

TWP. 15, RANGE 9 E, W.M.

CORNER No. 873

CORNER DESCRIPTION

SET 5/8" I.R. WITH
YELLOW PLASTIC CAP
"HRC" FROM WHICH A
12" CHINQUAPIN
BEARS S73°E, 10°
WITH YELLOW METAL
TAG.



HRC 1980

W.O. REF.

See card 282

CARD 1 OF 2

SECTION OR SUBDIVISION CW 1/16 sec 24


CORNER No. 873

TWP. 15, RANGE 9E, W.M.

CORNER DESCRIPTION

moved 5/8" I.R. 6.70'
north. Used tree
scrubbed in 1980.
Changed distance
& bearing to get
new corner.

RJA 1984



W.O. REF.

Over →

CARD 2 OF 2

This corner was moved in 1987
because the E 1/4 sec 24 moved
north. The corner set in 1980
was set using the Frey pipe at
the E 1/4. We proportioned the
new 1/4 cor in 1984.

RJA

873