

SECTION OR SUBDIVISION *Sec 17*

CORNER No. *1160*

TWP. *1N*, RANGE *11E*, W.M.

CORNER DESCRIPTION

*Set 5/8" rebar with  
yellow cap  
Tagged 16" Fir (Douglas  
S 40° W, 1.7' at  
HRC NE Property  
Corner*



W.O. REF. \_\_\_\_\_

CARD *1* OF *1*

HOOD RIVER COUNTY CORNER RESTORATION FORM

Section: 17 Township: 1N Range: 11E

Date: 10/31/11

Corner Designation

PROPERTY CORNER

Condition Report Only  
 Not Found  
 Renewed CORNER CARD 1160  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewals/Surveys, etc: 95090

HOOD RIVER COUNTY SET 5/8" REBAR w/CAP

Monument(s) & Accessories Found: (Condition and Source)

MONUMENT SET IN 95090 WAS DESTROYED. LOGGING IN THIS AREA HAS OCCURED SINCE MONUMENT WAS SET. BEARING TREE WAS CUT OFF ABOUT 7 FEET ABOVE THE GROUND.

Monument Detail

Sketch



Monument Set (Procedures and Description)

SET 5/8" REBAR w/CAP "B BESEDA PLS 50800"

New Accessories:

BEARING TREE ADDED - 8" FIR N 26°17'W 60.89'

Location & Comments:

Surveyor's Seal

Compass Declination 16°  
 Firm/Agency TENNESON  
ENGINEERING CORP.  
 Address 3313 W. 2ND. ST.  
SUITE 100, THE DALLES, OR.  
 Party Chief B. BESEDA  
 Notes B. HOFFMAN  
 Witness \_\_\_\_\_

