

1198

OREGON CORNER RESTORATION FORM

Section 6 Township 1 N Range 9 E

County Hood River Date September 13, 2013

CORNER DESIGNATION

South 1/16 Corner Section 6, T1N, R9E  
South 1/16 Corner Section 5, T1N, R9E

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. No previous record of this corner being established

Monument(s) & Accessories Found: (Condition and Source)

N/A

Monument Detail

Sketch



Monument Set (procedures and Description)

Set 3/4" x 24" Iron Rod with 2" Aluminum cap at midpoint between the found east 1/4 corner and the found south east corner of section 6

New Accessories

Referenced 3" Hemlock N45°W at 12.2' not scribed; 8" D. Fir N65°E at 2.5'scribed [1/16 S5 BT]; 6" Cedar S20°E at 1.0' scribed [1/16 S5 BT]; steel fence post north at 3.0'

Location & Comments  
No comments

Compass Declination 16°E

Firm/Agency:  
Ford Land Surveying  
PO Box 353  
Klickitat, WA 98628  
Party Chief: George Ford  
Notes: Field Book - 2013-4  
Witness: Beverly Ford

Surveyor's Seal



RECEIVED NOV 13 2013