SECTION OR SUBDIVISION

CORNER NO. 285

CORNER DESCRIPTION BASALT STONE 12×8×4 TON TOP GEROVES ON S. JE. SIDES HEM. 30" S 41 % 16' D.F. RSTUMT 36'S. 24° W. 1959 V D.F. COR APROX 2000'41 ad FOREST BOONDRY SIGN ON M.T. Hood hoop Highway

W.O. Ref. CARD OF

DREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT HOOD RIVER County Surveyor's Office
--

SECTION 1 TOWNSHIP 2 SOUTH	TH 9 EAST
COUNTY: HOOD RIVER	DATE SEPT 28, 2009
CORNER DESIGNATION: A-25	(Please check one)
Northeast Section Corner of Sec	<u>,</u>
Previous Renewals / Surveys, etc. Original: GLO Surveyor Fred Mensch, 1913, set a basalt stone 18x12x10 for closing corner to T2S, R9 & 10E,	x12x10 for closing corner to T2S, R9 & 10E, and marked
A 18" Fir bears S42°E, 29 lks (19.14 ft) marked "T2S R10E S6 BT". A 30" Fir bears S42°E, 29 lks (19.14 ft) marked "T2S R9E S1 BT". In 1981, Danny Cron, PLS#1028, found marked stone of record, as noted in CS#81087. In 1983, Larry Bishop, PLS#896, found a 6x11x5 stone 1.91 feet north of line, with "X" on top and 2 GLO BT's. Set a 2 ½" × 30" aluminum pipe with a 3" aluminum cap on the Township line, and establishes one new BT, a 6" White Fir bears S55°W, 34.4 ft. scribed "T2S R9E S1CC BT". (As shown in CS#83077)	DE S6 BT". S1 BT". record, as noted in CS#81087. .91 feet north of line, with "X" on top and 2 GLO BT's. He in the Township line, and establishes one new BT, a 6" BT". (As shown in CS#83077)
Monument(s) & Accessories Found: (Condition & Source On September 28, 2009, Tim Rouse, Fred Thomas, and 3" above ground in a ring of stone, in good condition. Th S42°E, 19.1 ft. The SW GLO BT is now a 36" D.Fir stur 4.0 ft. Bishop's SW Wt.Fir BT is now a 7" Wt.Fir, with pa	Monument(s) & Accessories Found: (Condition & Source) On September 28, 2009, Tim Rouse, Fred Thomas, and Don Karsch found Bishop's 1983 aluminum pipe & cap, 3" above ground in a ring of stone, in good condition. The SE GLO BT is now a 32" D.Fir with healed face, bears S42°E, 19.1 ft. The SW GLO BT is now a 36" D.Fir stump, 6 ft tall, with face and scribing visible, bears S40°W, 4.0 ft. Bishop's SW Wt.Fir BT is now a 7" Wt.Fir, with partially healed face & scribing visible, bears S53°W, 34.6 ft.
Monument Detail: 1983 Aluminum Cap is Stamped:	Sketch:
R9E R10E AM T1S CC T2S <u>S11S6</u>	Oh: CO
1983 PLS 896	BISHOP BT * 34 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Monument Set (Procedures and Description): No new monument set. We cleared, blazed, and replaced bo along the south line of Section 31, for the U.S. Forest Service	: and replaced boundary posts with orange carsonite posts, west, 3. Forest Service.
New Accessories: On September 28, 2009 we established 2 new bearing trees. A 14" White Fir bears S22°W, 31.8 ft, scribed "T2S R9E S1 AMCC BT". A 12" Cedar bears N21°E, 29.4 ft, scribed "T1S R10E S31 AMCC BT".	ed 2 new bearing trees. S1 AMCC BT". s1 AMCC BT".
Nailed a 1 ½" brass washer "PLS2799" in the bottom face of new bearing trees Location & Comments: Corner is 2082 ft. west of Cooper Spur Road. Corner is on north slope, south of drainage, in heavy timber of cedar, hemlock, and fir. Distances to bearing trees are to a nail at side center. All bearing trees have a "54-3 BT" sign nailed on the front and a "54-9 Land Survey Monument" sign nailed to the back, and a 6" orange painted head Set orange fiberclass not 4" east & 3" wast of monument	e of new bearing trees. r Spur Road. Der of cedar, at side center. r and a "54-9 orange painted
1	SURVEYOR'S SEAL
Party Chief: Timothy P. Rouse, Oregon PLS #2799	
Notes	
Witness: Fred Thomas, Oregon PLS #1018 Don Karsch, Oregon PLS #1946	

N 0285