

SECTION OR SUBDIVISION

C 5 1/16 SEC 34

CORNER No.

506

TWP. 3N, RANGE 10 E, W.M.

CORNER DESCRIPTION

IRON ROD REPLACED
BY BRASS CAP SET
IN MONUMENT
CASE BY H.R.CO.
12/23/70

W.O. REF.

CARD

OF

CC0506
12/23/70

SET BRASS CAP IN
MONUMENT CASE

C
|
1/16 — 534
|
C

T3N R10E

B.C. REPLACES IRON ROD
LOCATED IN INTERSECTION
OF FRANKTON & FAIRVIEW

W.C. Brown