

SECTION OR SUBDIVISION

TWP. 2 N, RANGE 10 E, W.M.Found by L. Bishop L.S. #896
& J. P. Robinson Nov. 1976Reference Henderson
survey & notes 1908W.O. REF. 76268CORNER No. 763
N. 1/4 cor. Sec. 14

CORNER DESCRIPTION

Found 3/4" Gas
Pipe 1.5' under
surface of Ground
set 5/8" Iron Rod
Flush with surface.
D.S.F.S. Location
tag on Power Pole
South

CARD 1 OF 2

SEE 2 OF 2

SECTION OR SUBDIVISION

$\frac{1}{4}$ cor $\frac{11}{14}$


CORNER No.

763

TWP., RANGE

2N, RANGE 10 E, W.M.

CORNER DESCRIPTION



Fd 2" IP
w/ lead plug.

25' west of
 $\frac{3}{4}$ " pipe fd by
Bishop.

2" pipe fits
L. Henderson. Plat
also fits 25' road
OVER \rightarrow

W.O. REF. _____

CARD

2

OF

2

Accepted 2" I.P. as true
corner.

Dick Arnold
Dec. 1986

Cor#763 ¼ cor 11/14 2N10E

Larry Bishop found a ¼" pipe in 1976 and set a 5/8" rod over found pipe. HRC found a 2" pipe w/lead cap in 1986 25.0' west of bishop's rod. This 2" pipe fits Henderson's 1909 plat and the 25' platted road. The 2" pipe also fits the section corner to the east within a few tenths. HRC accepted the 2" pipe as being the true corner.