SECTION OR SUBDIVISION 5 1/6 22 23	Corner No. 769
Twp. / 4 , RANGE 9 E , W.M.	CORNER DESCRIPTION
	5 1/16 between
4	Secs 22:23
with tag	
المالية	one BT/Tag
W 80 3. A'	6" Doug-fix Bears
* Set 1"IP	N 80° E 3,45+
9	
* 9	
W.O. Ref. 17-76	
Set by Single Proportion	
	CARD OF

HOOD RIVER COUNTY CORNER RESTORATION FORM

Section: 22 Township: |N Range: 9E

Date: 7/13/11

Corner Designation

5 1/6 BETWEEN 22 \$ 23

____Condition Report Only

Not Found

X Renewed CORNER CARD 76

Unrecorded
Surveyed In

Referenced Out

Previous Renewals/Surveys, etc: 17-76

SET BY SINGLE PROPORTION

Monument(s) & Accessories Found: (Condition and Source)

OZ M FOUND I" PIPE BEARING RET UP 05 FOUND- 6" DOUG FIR SNAG

Monument Detail

10 FIR

Sketch

6"DOUS FIR SNAG

9620

N80°E

Monument Set (Procedures and Description)

New Accessories:

BEARING TREES PAINTED WITH RED AND BLUE BANDS,
Incation & Comments: SET ALUM, NAIL IN SIDE OF TREE AND NEW BEARING TREE-10" FIR NORTH 64°WEST TAG IN FAC

Compass Declination 19°
Firm/Agency TENNESON
ENGINEERING CORP.
Address 3313 w. 2ND, 57,
Address 3213 w. 2ND, 57,
Address

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
JULY 13, 1989
BENJAMIN B. BESEDA

50800 EXPIQES: 12-31 11