SECTION OR SUBDIVISION	718 1817 CORNER No. 818
TWP. 2 N , RANGE II	
*	FO. 12" I.P. (AT CORNER OF
	FENCE) REPLACED W/ 2"
Ch X	I.P. AND BRASS CAP. FO
	POTTED DAK W/ POSSIBLE
X	BLAZE SI6°W. ESTABIS ED B.T.: 15" DAK N75°W.
	192' DIST. NOT MANY TREE
	AROUND.
W.O. REF. REVSTO, BY H.R. Co.	CETA
CREW 1/78	
	OF

Cor#818 sec cor 7/8/17/18 2N11E

HRC fd  $\frac{1}{2}$ " IP at fence corner in 1978. Replaced with 1  $\frac{1}{2}$ " IP and cap. No orig evidence, and this corner does not fit Henderson distance to the  $\frac{1}{2}$  cor to the west. Other surveyors have searched for the orig corner without success.