RANGE 849 E, W.M.	CORNER DESCRIPTION
	264 IP
	w/brass cap
	Cox Lorry Bish
Found Orig. 60" Now 60" 9. Eir 5.	tump 585 E 4.6'
Ses E 4.6	
	ned 14525 BT
	Found orig. 60" Now 60" D. Fir 5

## OREGON CORNER RESTORATION FORM

Section 30 Township 1N Range 9E

County Hood River Date September 26, 2011

## CORNER DESIGNATION

West 1/4 Corner Section 30, T1N, R9E East 1/4 Corner Section 25, T1N, R8E

X Condition Report Only

\_\_\_ Not Found \_\_\_ Renewed

Unrecorded

Surveyed in
Referenced Out

Corner was established by Newton Clark by GLO Surveying in survey for U.S.D. Forest Service, Region 6, filed November 5, 1980, CS-80091 accepted and Survey by Bishop 1884. Previous Renewals/Surveys, etc. remonumnented this position. survey commenced June 9,

Monument(s) & Accessories Found: (Condition and Source)

Found 2-1/2" Pipe with 2-1/2" brass cap, 60" Fir stump S85°E at 4.6'; 26" Fir N10°W at healed scar.

Monument Detail

Sketch

60" STUMP FOUND 212" PIPE S WITH 212" CEBSS COP IN MOINMO OF STANK STEEL FENCE POS BY MONDINGENT

Nor to scale

Monument Set (procedures and Description) N/A

New Accessories

No new accessories added

Location & Comments No comments

Compass Declination 16°E Firm/Agency:
Ford Land Surveying
PO Box 353
Klickitat, WA 98628
Party Chief: George Ford
Notes: Field Book – 2011-4
Witness: Brett Crooks

Surveyor's Seal

