Section or Su	JBDIVISION	(2)	7	Corne	r No	1081
T_{WP} . $2N$, RANGE	7+8	€_, W.M.		CORNER I	DESCRIPTION
W.O. Ref	9)	Set in error the Hood Riv correct posit Orig. 34" nor NBI 3/4W 17 Bearing trees 20" now 26" 18" now 8" I unrecorded n Set Mon. 26" MARKED: I6" D-Fir	from B.P.A. tiever County Surion from the B w 50" sawed, "2"ks) remains a marked by H. " D-Fir S64W D-Fir SHE 19.0 low 26" D-Fir in ground in TNIOW 34.1" se	ent set by Hoode to the Orig, st veyor replaced in P.A. tie. rotted D-Fir student of healed blaze ond River County 14.2' (record S7 (record S15E 15, N77E 10.5' heal a stone & earth cribed T2NR7ES ty monument ne	one. As author their monume imp N80W 4 obvious on big y OW 10.65") healed to ed blaze in mound 3" b	orized by nt in the 4.1' (record ark nealed blaze ase to top
(5	# 0	8704	7			
				CARD		OF

HOOD RIVER COUNTY

T 2N . R 8E , W.M.	Corner Code No. CC 1081					
Segregated Surveys:						
Name SE corner, Section 12 (DLC, HES, Tract, Mining Claim, Indian Allotment, Fe	Corner Noderal Reserve, Townsite)					
1. History of Corner Establishment and Subsequent Restorat	ion:					
Corner was established in 1975 by Hood River County Survinformation from Bonneville Power Administration Bonnevidrawings.						
2. Description of Evidence Found:						
A search was made for the corner and not found. One bearing tree with tag was found but no record of tree exists.						
3. Describe Monument, Accessories and Corollary Data to Pe Diagram corner and indicate meridian and reference to m	ap of record. Surveyor's					
Field Book No. 3-75 Page No. Date of work	•					
Section Corner is 2 inch iron pipe with brass cap 20" douglas fir scribed, with tag bears S 70°W 10.65 fee south side 2 feet up. 18" douglas fir scribed, with tag, bears S 15°E 15.20 fe						
side 2 feet up.	et to hall with shinel on east					
	and the second					
Oregon Plane Coordinates: North Zone, X 1,647,143.	04 Y, 730,523.898					
Second Order Accuracy. Derived from:	•					
Pin Pointed on Photo No DateLocated						
NOTE: X = Easting Y = Northing						

CC1081

2" iron pipe with brass cap

25000125	TON OF OURVEY CTATION	STATE	OREGON	
DESCRIPT	ION OF SURVEY STATION	COUNTY HOOD RIVER		
NAME OF ST	ATION SE Corner Section 12 T2N, R7EWM	JOB NO.	18-75	
	RTY David Downing FIELD NOTES same		ATE 11-18-75	
STATION MARK	SURVEY POINTS AND PROMINENT OBJECTS WHICH CAN BE SEEN FROM GROUND STATION	DISTANCE	BEARING	
Contract Con				
S-1	1" iron pipe with yellow plastic cap marked HRC	166.22	N87°45′ 26"E	
		9 - 7		
		o _e v		
			*	
	NOTE: All bearings and distances are Oregon State Plane Coordinates, North Zone			

20" Doug Fir Set 2 finish nails on South side 2 ft. up

570°W - 15

18" Doug. Fir Set 2 finish nails East side 2 ft. up.