

SECTION OR SUBDIVISION $\frac{1}{4}$ or $\frac{1}{2}$
TWP. 2N, RANGE 10E, W.M.

CORNER No. 1176

CORNER DESCRIPTION

C.O. surveyor searched
for Gait stone
on 12/9/02. Not FD.
Position of corner
as per CS # 95111
appears to be correct.
~~_____~~
~~_____~~

W.O. REF. _____

CARD OF

Cor# 1176 1/4cor between secs 1&12 2N10E

Goit set stone from 2 orig bt's in 1898. JLH fd said stone several times from 1902-1907. Orig oak still standing, fir stump still showing marks. P M Morse fd same evidence in 1909. HRC surveyor searched for stone & BT's 12/9/02, did not find. Also checked with PP&L in Dec., 2002 for any record of this corner, unsuccessfully. 24" DF with chopped face is about 15 feet NE of our calc. position, but we have found no notes for this tree. Terra Surveying found two JLH mons about 1/4 mile westerly of the 1/4 corner in Dec 2002 that fits our calc position very closely. Position of corner as shown on G E Raleigh plat for PacifiCorp, 1995, CS#95111, appears to be correct, as it fits JLH distances to corners in all four directions. Cron used a GLO proportioned position for several surveys, but we feel that the G E Raleigh position more closely represents the original 1/4 corner.