DEPARTMENT OF PUBLIC WORKS CARLOS VAN ELSBERG, DIRECTOR P. D. BOX 457

HOOD RIVER, DREGON 97031 PHONE 386-2616



COUNTY OF HOOD RIVER BOARD OF COMMISSIONERS

P. F. BUCKLIN, CHAIRMAN JAN Y. KURAHARA, VICE CHAIRMAN JERRY ROUTSON CLARENCE N. AMOTH BRUNG HUKARI

> HOOD RIVER, OREGON May 14, 1970

Neal Creek Park, Section 36, Township 2 North, Range 10 East of the Willamette Meridian, Hood RESUME : River County, Oregon.

On March 20, 1970, the Hood River County Survey Department began a search for corners in Section 36 near Neal creek. The purpose of this search was to locate the corners on the Southeast quarter of the Southeast quarter of said section. This parcel was to be acquired by the County through an exchange with the East Fork Irrigation District for park purposes.

The search was begun at the East quarter corner of Section 36 where a 2 inch iron rod, about 1 foot above the ground was found, Proceeding Southerly one quarter mile along the Section line, no one sixteenth corner was found but about one quarter mile further South a large stone in a mound of smaller stones was found in an old wire fence line. Two BT's were found and the corner was accepted as the Southeast corner of Section 36. Proceeding Westerly, crossing Neal creek and Neal Creek Loop Road, no one sixteenth corner was found but a 3/4 inch pipe for the South quarter corner of Section 36 was found, along with a l inch square iron bar that had been removed from the ground. This bar was recorded in an earlier survey as the South quarter corner of said Section 36. Proceeding Northerly, the one sixteenth corner, a 1-1/2 inch pipe was found. Continuing North, no center quarter was found. A recorded reference pipe, 20.0 feet East of the North quarter corner of Section 36 was located but no point was found for the North quarter corner. The West quarter corner of Section 36 was found to be 1-1/2 inch pipe set along side a stone with an "X" in the top. Two BT's were found here.

A traverse tying all the found corners and the average centerline of Neal Creek Road was run using a Theodolite, steel tape and electronic distance measuring instruments. All the field information was compiled, computed and plotted on a working drawing and all the corners found were accetped. Using this information, positions for the one sixteenth corners in the Southeast quarter of the Southeast quarter were computed on a proportional basis.

Resume': Neal Creek Park

page 2

All corners set were 2 inch pipe with 3 inch brass disks. The stone for the Southeast corner of Section 36 was also replaced with a 2 inch pipe with a 3 inch brass disk and four new BT's were taken on this corner.

All information concerning monumentation is on file in the Hood River County Surveyor's Office.

Carlos Van Elsber

Director,

Department of Public Works

