

CS7215

FILED

October 6, 1971

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

APR 18 1972
Carlos L. Van Elsberg
COUNTY SURVEYOR
DEPUTY

CLEAR CREEK ROAD CONTROL SURVEY
SECTION 18 T1S, R10EWM.

Carlos L. Van Elsberg
**OREGON
JULY 12, 1963
CARLOS L. VAN ELSBERG
625**

In August of 1971 the Hood River County Road Department requested a survey to establish the corner monuments which control, by deed reference, the centerline of Clear Creek Road. These points would fix the North-South centerline of Section 18, T1S, R10EWM and the East-West centerline through the Southwest quarter of Section 18 T1S, R10EWM.

The South and East lines of Section 18, T1S, R10EWM were established during the Antoine Timber Sale Survey in Sections 17, 19 and 20, T1S, R10EWM. A search for corners disclosed the following monuments in Section 18 T1S, R10EWM:

Section Corner on the range line common to Sections 7 and 18, T1S, R10EWM and Sections 12 and 13, T1S, R9EWM - Found 2" axle as per 1959 Hood River County Surveyor.

North quarter corner to Section 18 - Found iron bar 8" deep in centerline of Clear Creek Road.

West quarter corner to Section 18 - Found 1" iron pipe. This point was later determined erroneous in both line and distance so was not used.

Southeast corner of Section 13 T1S, R9EWM - Found 1" iron pipe and original stone, also B.T. with scribe still readable as per 1911 re-survey.

North 1/16 of Section 18 T1S, R10EWM on range line. No monument found but found one B.T. with visable scribe as per 1911 survey notes.

All this evidence was tied by a traverse to the Antoine data then plotted and and compared to the 1884 and 1910 G.L.O. surveys and the 1911 County survey.

An additional traverse was extended Northerly to the Northwest corner of Section 7 T1S, R10EWM, being an iron axle re-established by the County Surveyor in 1959 to confirm the Northwest corner of Section 18 T1S, R10EWM.

Clear Creek Road Control Survey
October 6, 1971
page 2

The West quarter corner and the 1/16 corners on the West line of Section 18 were re-established by single proportion. The East quarter corner and the Southeast corner of Section 13, T1S, R9EWM were set at this time. The center quarter of Section 18 was re-established by intersection. The center south 1/16 corner was re-established by an equal division of the distance from the new center quarter to the South quarter corner of Section 18 T1S, R10EWM.

The re-established corners, the re-monumented corners and corners left as found, including sixteenth corners, are described on the plat of this survey and all accessories, such as witness trees, tags and references are recorded, filed and indexed in the office of the Hood River County Surveyor along with the field notes and computation sheets.

DEPARTMENT OF PUBLIC WORKS
 CARLOS VAN ELSBERG, DIRECTOR
 P. O. BOX 457
 HOOD RIVER, OREGON 97031
 PHONE 386-2616



COUNTY OF HOOD RIVER
 BOARD OF COMMISSIONERS

P. F. BUCKLIN, CHAIRMAN
 JAN Y. KURAHARA, VICE CHAIRMAN
 JERRY ROUTSON
 CLARENCE N. AMOTH
 BRUND HUKARI

HOOD RIVER, OREGON

October 21, 1971

Resume' of Survey: Clear Creek Road Control Survey for Hood River County Road Department.

Location: Section 18, Township 1 South, Range 10 East WM, Hood River County, Oregon.

Date Completed: October 6, 1971

Crew: B. Wells E. Graham
 W. Brown L. Lesselyoung
 R. Arnold. R. Smith

References: G. L. O. Field Notes and Plats surveyed in 1884 and 1910. Hood River County Surveyor Field Notes and Plat Surveyed in 1911, Mylar drawing showing Section 18, T1S, R10EWM.

In August, 1971 the Hood River County Road Department requested a survey to establish the corner monuments which control, by deed reference, the centerline of Clear Creek Road. These points would fix the North-South centerline of Section 18, T1S, R10EWM and the East-West centerline through the Southwest quarter of Section 18, T1S, R10EWM.

The South and East lines of Section 18, T1S, R10EWM were established during the Antoine Timber Sale Survey in Sections 17, 19, and 20, T1S, R10EWM. A search for corners disclosed the following monuments in Section 18, T1S, R10EWM

The Section Corner on the range line common to Sections 7 and 13, T1S, R10EWM and Sections 12 and 13, T1S, R9EWM - Found 2" axle as per 1959 Hood River County Surveyor.

The North quarter corner to Section 18 - Found iron bar 8" deep in centerline of Clear Creek Road.

The West quarter corner to Section 18 - Found 1" iron pipe. This point was later determined erroneous in both line and distance so was not used.

The Southeast corner of Section 13, T1S, R9EWM - Found 1" iron pipe and original stone, also B.T. with scribe still readable as per 1911 re-survey.

Resume'

Clear Creek Road Control Survey

October 21, 1971

page 2

All this evidence was tied by a traverse to the Antoine data then plotted and compared to the 1884 and 1910 C.L.O. surveys and the 1911 County survey. An additional traverse was extended Northerly to the Northwest corner of Section 7, T1S, R10EWM, being an iron axle re-established by the County Surveyor in 1959 to confirm the Northwest corner of Section 18 T1S, R10EWM.

The West quarter corner and the 1/16 corners on the West line of Section 18 were re-established by single proportion. The East quarter corner and the Southeast corner of Section 13, T1S, R9EWM were set at this time. The center quarter of Section 18 was re-established by intersection. The center south 1/16 corner was re-established by an equal division of the distance from the new center quarter to the South quarter corner of Section 18, T1S, R10EWM.

The re-established corners, the re-monumented corners and corners left as found, including sixteenth corners, are described on the plat of this survey and all accessories, such as witness trees, tags and references are recorded, filed and indexed in the office of the Hood River County Surveyor along with the field notes and computation sheets.

Respectfully submitted,



Ed Graham
Chief of Party

EG:mw