3231 S.E. 50TH PORTLAND, OREGON 97206 PHONE 774-1154 950 NORTHWOOD DRIVE, N.E. SALEM, OREGON 97301 PHONE 363-1541

Glenn D. Strait REGISTERED LAND SURVEYOR

LAND PLANNING CITY LOTS ACREAGES SUBDIVISIONS RECEIVED 74

TOPOGRAPHIC MORTGAGE TIMBER HOUSE PLANS

March 22, 1974

Job Resume

Of survey of the N.W. 4 of Section 19, T 1 N, R 10 E, WM.

I ran a traverse line from the North $\frac{1}{4}$ corner of Section 19, West to the Northwest corner of Section 19. I found an iron pipe and brass cap with witness trees. At about halfway though I found a 1 inch iron pipe bent over from farm equipment and off the fence line, which proved to be 2.53 south of line and 6.93 West of relocated 1/16 corner. relocated this corner by single proportionate measurement. I ran a traverse South and found the West $\frac{1}{4}$ corner , a 1 1/2 inch iron gas pipe as shown on John Henderson survey. I then ran traverse East and found iron bolt for 1/16 corner, as shown on Henderson survey. I ran on out to center of section a la inch iron pipe at edge of road. I then managed a wiggle point on an offset sighting to south 1 corner and North 4 corner to prove 14 inch iron pipe for center of Section. Accepted it. I then ran North with traverse to the N $\frac{1}{4}$ corner to close my work out which worked out to be good, a 0.28 error. I divided the ‡ section up as shown on my survey plat. I set the center of Gov'nt lots 1 and 2 and ran from there on true line S 89057' W 718.88 feet to the West line of Section 19 and set an axel 2.5 feet East of a iron bolt that we found as per Henderson plat.



井神神

NOV 2 9 1976

COUNTY SURYEYOR

DEPUTY