

CONSULTING
Engineers TENNESON ENGINEERING CORPORATION

January 31, 1983
Work Order No. 6338

PHONE (503) 296-9177
409 LINCOLN STREET
THE DALLES, ORE. 97058

FIELD NOTES: Survey for John F. Cushman

CREW: David L. Tuttle, Partychief
Lawrence E. Jones, Assistant

REFERENCES: Tenneson Engineering Corporation prior Work Order X-236.
Hood River County Survey done by George Frey, date and
recording number unknown.

In August 1983, Tenneson Engineering Corporation was retained by John F. Cushman to locate pins on a tract of ground previously surveyed by Wall and Tenneson in 1954, located in Sections 27 and 34, Township 3 North, Range 10 East, Willamette Meridian. The intent of the survey was to recover the prior monuments and re-establish additional points on a parcel acquired from the State of Oregon Highway Department.

Prior to undertaking the work, we researched our records and recovered our prior Work Order X-236 which was the survey of the original Cushman parcel. Mr. Cushman provided us with a copy of a map and description believed to have been prepared by George Frey indicating the other parcel.


Work was started by attempting to locate the prior set monuments. After considerable search only two of the points were found on the first leg of the description which was only 32 feet long. This was felt too short a sight to attempt to reconstruct the survey. Therefore, turned the angle from the one found point on the section line in an attempt to recover the section corner 26, 28, 33, and 34. Initial search uncovered a 2½" iron pipe with lead plug and tack in the approximate location this corner. This pipe was known by our partychief to have been set by Mr. Norm Newton several years ago. It did not appear to fit the information shown on the other survey which indicated the corner to be Corps of Engineers brass cap. After additional search and excavation, the original Corps of Engineers brass cap was recovered in good condition. The 2½" iron pipe found apparently lays on the section line 26 feet to the north. The section line was then pushed through to the north one-quarter corner of Section 34, also a Corps of Engineers brass cap, and then the survey traverse laid out pursuant to the original deed descriptions

Field Notes
John H. Cushman
January 31, 1983
Work Order No. 6338
Page -2-

and survey plat.


All corners not found were re-monumented with 5/8" iron rods with the additional corners requested by Mr. Cushman set as directed.

Corners found, set, distances and angles measured shown on the attached map of survey for John Cushman, Tenneson Engineering Corporation, Work Order X-236, Revision 1, which by reference is made a portion of these notes.



David L. Tuttle

David L. Tuttle, Oregon Land Surveyor #7872



CHECKED AND APPROVED:

Tenneson Engineering Corporation

Donald J. Branton

Donald J. Branton, President

