



1/4 COR.
7 ⊕ 8

660.0' CALC.

FD. I.P. 74' WEST & 402' SOUTH OF CALC. POSITION

FD. I.P. 11' EAST & 2.4' SOUTH OF CALC. POSITION

DETAIL 2
SCALE 1"=10'

FD. RR SPIKE 0.9' EAST & 6.7' NORTH OF CALC. POSITION

DETAIL 3
SCALE 1"=10'

FD. 1/2" I.P.
CALC. POSITION
FD 1/2" I.P.
SEE DETAIL 2

N 89° 27' 44" E 661.60'

FD. RR SPIKE
CALC. POSITION
SEE DETAIL 3

N 0° 25' 39" W 660.0' CALC.

FD. I.P. .3' EAST & 2.5' NORTH OF CALC. POSITION

DETAIL 1
SCALE 1"=10'

SEE DETAIL 1
FD 3/4" I.P.
CALL POSITION 1/16 COR.

1320.0' CALC.

7 ⊕ 8
18 ⊕ 17
T2N RIDE
SCALE 1"=50'

#1372

NOT A FILED SURVEY!
FOR INFORMATION ONLY

REVISED 6/4/73 W.L.B.

HOOD RIVER COUNTY SURVEY OFFICE	
PORTION SECTION 8 T2N RIDE	
DATE: 3/21/73	JOB NO. _____
SCALE: AS SHOWN	FILE NO. _____
DRAWING: W.L. BROWN	SHEET 1 OF 1
CHART-PAX, INC. LEEDS, MASS. SP# 3672 3-8 7-65247-053 1372	

September 10, 1971

FIELD NOTES:

FOR: Resurvey and Legalization of York Hill Road

WORK PERFORMED BY: Hood River County Survey Department

In researching York Hill Road, it was found that the road, as built, did not follow the right of way as described in the original road case; therefore, in July of 1970 the Hood River County Survey Department began a survey of York Hill Road to provide an as built location for mapping prior to legalization proceedings to acquire additional right of way and vacate the unused right of way.

The traverse began at the quarter corner between Section 8 and 9, Township 2 North, Range 10 East of the Willamette Meridian. It ran along York Hill Road to Binns Hill Road; thence along Binns Hill Road and terminated at the quarter corner between Sections 17 and 18, Township 2 North, Range 10 East of the Willamette Meridian. The traverse was closed by using Hood River County control point Nard as a point in the traverse. Closing angles were turned from and to points in the traverse and the distances were measured with Tellurometers. Bearings were based on solar observation. Field notes are filed in Book 70-6

Corners Found:

The quarter corner between Sections 8 and 9, Township 2 North, Range 10 East of the Willamette Meridian - an iron pipe which has since been replaced by a Hood River County Brass Cap in a monument case.

The center quarter corner of Section 8, Township 2 North, Range 10 East of the Willamette Meridian, - a 3/4" iron pipe referenced by an aluminum tag posted by the County Surveyor, dated 1959.

The corner common to Sections 7, 8, 17 and 18, Township 2 North, Range 10 East of the Willamette Meridian - an 1-1/4" iron pipe. No B.T.'s or other evidence was found to prove this pipe to be a true corner.

The quarter corner common to Sections 17 and 18, Township 2 North, Range 10 East of the Willamette Meridian - a 1" iron pipe. No evidence was found to support this pipe as a true corner. The property owner, Mitz Tamiyasu, said this pipe was a 6.0 foot offset to the quarter corner which was set by Doug Button when he was the County Surveyor.

I certify that this work was done under my direct supervision.

FILED

SEP 13 1971

Carlos Van Elsberg
COUNTY SURVEYOR

By

DEPUTY

Carlos Van Elsberg
Carlos Van Elsberg
Director
Department of Public Works