



County Road Deeded Commissioners
Journal A, Page 213, Nov. 3, 1904.

Plat of George Shitara tract located in the NW $\frac{1}{2}$ of the NW $\frac{1}{4}$ of Sec. 36, T2N, R10E of the Willamette Meridian.

Beginning at the SE corner of the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Sec. 36, T2N, R10E of the Willamette Meridian, thence N 89° 18' 40" W 150 feet, thence N 00° 21' 00" E 145 feet, thence S 89° 18' 40" E 150 feet, thence S 00° 21' 00" W 145 feet to the point of beginning.

This plat correctly represents a survey made under my direction in conformance with the requirements of the Oregon Land Surveyors Laws at the request of Mr. C. Shitara. There are no visible encroachments other than those shown hereon.

Roy L. Hill

REGISTERED
OREGON
LAND SURVEYOR

Roy L. Hill

JULY 3, 1969
ROY L. HILL
578

FILED

JUL 10 1969

Curtis Van Elsberg
COUNTY CLERK

By _____
DEPUTY

J.S. DIELSCHNEIDER & ASSOC INC
HOOD RIVER, ORE.
SURVEY BY JEM B RLH JUN 9, 69
DRAWN WCB JUNE 16, 1969
SCALE 1"=40' DRWG 6935

1459
7-599

2ND OF 36 #1

CS1459

JAMES S. DIELSCHNEIDER & ASSOCIATES, INC.
Engineering & Management Consulting

Portland: 503 232-4901
The Dalles: 503 296-9134
Hood River: 503 386-2912

836 N.E. Laurelhurst Place
Portland, Oregon 97232
606 State Street
Hood River, Oregon 97031

June 17, 1969

Mr. Carlos Van Elsberg, Director
Department of Public Works
Hood River County
P.O. Box 457
Hood River, Oregon 97031

FIELD NOTES:

George Shitara, Project No. 6935, survey in E $\frac{1}{2}$ NW $\frac{1}{2}$ NW $\frac{1}{2}$ Sec. 36, T2N, R10E WM.

CREW: R. L. Hill, Party Chief
J. G. Mahoney, Instrumentman
R. L. Smith, Chainman

DATES PERFORMED: May and June, 1969

WEATHER: Fair, warm

On May 14, 1969, our firm was retained by Mr. George Shitara to establish the boundaries of a parcel of land located within the NW $\frac{1}{2}$ of the NW $\frac{1}{2}$ of Sec. 36, T2N, R10E WM.

We referred to Hood River County Map No. 2N 10 36 which showed the corners in the vicinity. We also referred to plats of previous surveys filed in the office of the county surveyor.

The boundaries of this parcel were established from a survey beginning at the NE corner of the NW $\frac{1}{2}$ of Sec. 36. Iron pipes were set at the NE corner, the NW corner, the SW corner and 20 feet west of the SE corner of the property.

Monuments found and set, together with the measured distances and bearings used on this survey, are shown on the attached map, which is by reference made a part of these notes.

I certify that this work was done under my direct supervision.

REGISTERED
OREGON
LAND SURVEYOR

Roy L. Hill
JUL 9 1969
ROY L. HILL
578

rz

FILED

JUL 10 1969

Carlos Van Elsberg
COUNTY SURVEYOR

By _____
DEPUTY

REGISTERED PROFESSIONAL
ENGINEER
6092
OREGON
JAMES S. DIELSCHNEIDER, P.E.
EXPIRES 8, 1968
DIELSCHNEIDER

2N10E 36 #1