



FILED
 JUL 16 1970
Carlos Lyman Van Elsberg
 COUNTY SURVEYOR
 DEPUTY

REGISTERED
 OREGON
 LAND SURVEYOR
Carlos Lyman Van Elsberg
 JULY 12, 1963
 Carlos Lyman Van Elsberg
 623

#3

REVISED 8/30/71 wcb

HOOD RIVER COUNTY SURVEY OFFICE	
PLAT OF SE 1/4 SEC 36 T2N R10E WM HOOD RIVER COUNTY	
DATE: 6 3 70	JOB NO. _____
SCALE: 1" = 300'	FILE NO. _____
DRAWING: NARD	SHEET <u>1</u> OF <u>1</u>

DEPARTMENT OF PUBLIC WORKS
 CARLOS VAN ELSBERG, DIRECTOR
 P. O. BOX 457
 HOOD RIVER, OREGON 97031
 PHONE 386-2616



COUNTY OF HOOD RIVER
 BOARD OF COMMISSIONERS

P. F. BUCKLIN, CHAIRMAN
 JAN Y. KURAHARA, VICE CHAIRMAN
 JERRY ROUTSON
 CLARENCE N. AMOTH
 BRUNO HUKARI

HOOD RIVER, OREGON

May 14, 1970

RESUME': Neal Creek Park, Section 36, Township 2 North,
 Range 10 East of the Willamette Meridian, Hood
 River County, Oregon.

On March 20, 1970, the Hood River County Survey Department began a search for corners in Section 36 near Neal creek. The purpose of this search was to locate the corners on the Southeast quarter of the Southeast quarter of said section. This parcel was to be acquired by the County through an exchange with the East Fork Irrigation District for park purposes.

The search was begun at the East quarter corner of Section 36 where a 2 inch iron rod, about 1 foot above the ground was found. Proceeding Southerly one quarter mile along the Section line, no one sixteenth corner was found but about one quarter mile further South a large stone in a mound of smaller stones was found in an old wire fence line. Two BT's were found and the corner was accepted as the Southeast corner of Section 36. Proceeding Westerly, crossing Neal creek and Neal Creek Loop Road, no one sixteenth corner was found but a 3/4 inch pipe for the South quarter corner of Section 36 was found, along with a 1 inch square iron bar that had been removed from the ground. This bar was recorded in an earlier survey as the South quarter corner of said Section 36. Proceeding Northerly, the one sixteenth corner, a 1-1/2 inch pipe was found. Continuing North, no center quarter was found. A recorded reference pipe, 20.0 feet East of the North quarter corner of Section 36 was located but no point was found for the North quarter corner. The West quarter corner of Section 36 was found to be 1-1/2 inch pipe set along side a stone with an "X" in the top. Two BT's were found here.

A traverse tying all the found corners and the average centerline of Neal Creek Road was run using a Theodolite, steel tape and electronic distance measuring instruments. All the field information was compiled, computed and plotted on a working drawing and all the corners found were accepted. Using this information, positions for the one sixteenth corners in the Southeast quarter of the Southeast quarter were computed on a proportional basis.

Resume': Neal Creek Park
page 2

All corners set were 2 inch pipe with 3 inch brass disks. The stone for the Southeast corner of Section 36 was also replaced with a 2 inch pipe with a 3 inch brass disk and four new BT's were taken on this corner.

All information concerning monumentation is on file in the Hood River County Surveyor's Office.

Carlos Van Elsberg

Carlos Van Elsberg
Director,
Department of Public Works

FILED
JUL 16 1970
Carlos Van Elsberg
COUNTY SURVEYOR
BY _____ DEPUTY