

N.W. COR.
SEC. 33
Fd.-B.C. in M.C.

N. 1/4 COR.
SEC. 33
pos. as per
H.R.C. - not
tied into
N. 00° 22' 42" W.
(F.R.)
N. 00° 29' 20" W.
(F.R.)
263
#R.08 49

W. 1/4 COR.
SEC. 33
Fd.-B.C. in M.C.

E. 1/4 COR.
SEC. 33
calc. pos.
as per H.R.C.
Fd.-B.C. 165. & 111 W.

State Hwy 281 as per 3rd #195 dated 7/27/1922
R.I.O. as exists

set - RR spike
in existing E

N. 89° 16' 04" E.

397.23

430 - call

2657.50
as per H.R.C.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

JUNE 9, 1978

FILED

OCT 12 1978

COUNTY SURVEYOR

DEPUTY

sd SURVEY

FOR DON MULLER
LOCATION - SEC. 33,
T. 1N., R. 10E, W.M.,
HOOD RIVER COUNTY,
OREGON

SCALE = 1" = 100'

Basis of Bearing and
SEC breakdown as per
H.R.C. Survey dated 6/4/76

78059

11-022