

7 8
18 17
1/4 SEC. COR.
Found Brass Cap
as per record
8' East of Existing

2868.03'
N 0° 00' 00" E

2479'

499.89'

Existing T.L. 601-151017

Cooper Spur Road
State Hwy 35 Detour Road
Raveled - 32' base

Existing

18 17
1/4 COR.
Found marked Stone
as per record

Center of 24" White Fir root cavity
Found hole with uprooted 24" W.F. partially attached

NOTE: hole is in the western portion of what appears to be an ancient road bed - said road bed runs North & South being 15' to 20' wide



Scale = 1" = 100'
Assumed Basis of Bearing

REGISTERED PROFESSIONAL LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

May 13, 1983

D.L.C. SURVEYING
2001 Front Creek Rd.
Parkdale, OR 97131

"SURVEY"

FOR Eunice Kemp

LOCATION: Location of a particular tree which fell across Hwy. 35 detour route involving an auto accident, said tree located in the N.W. 1/4 of Sec. 17, T.15., R.10 E., W.M.

HOOD RIVER COUNTY, OREGON

FILED

AUG 01 4 1983

COUNTY SURVEYOR
Richard J. Arnold
DEPUTY