



Jarrative: As per O.R.S. 209.250 all required information is shown in its proper place. In Addition one could define Purpose of Survey as:

- 1.) Locate existing road as shown.
 - 2.) Define Property Lines as shown.
 - 3.) Resolve Boundary Line problem as discovered by H.R.C. 79095 Survey -
 - 4.) Resolve conflict between D.L.C. 1/31/83 Survey 1/2" I.R. and H.R.C. 79095 Survey 5/8" I.R. as shown -

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

JAN. 6, 1988

Basis of Bearing & Section
Control as per A.R.C. Jan. 1983
Survey filed as C.S. 85057

NOTE: Iron rod (I.R.) monuments set have yellow, plastic cap stamped "ES 1028" affixed -

SURVEY ⁸⁶ ^{A.W.}
R-Bob Zeman, Tim Schechitel & Judy Cobb.
CATION-Parcels located in the
East 1/2 of Sec. 15, T. 1 N., R. 10 E.,
W. M.-
**WOOD RIVER COUNTY,
OREGON**

**DLC SURVEYING
DAN CRON 352-6574
34 TROUT CREEK ROAD
ORKDALE, OREGON 97041**

FEB 23 1988
Pat. 9. Ardell

Proposed Boundary Adjustment
to correct possession line
problem involving improvement

Proposed Boundary Adjustment
to correct possession line
problem involving improvement -

~~Dist.~~ Gov't Lot 9
21° 57' W. Gov't Lot 16

16th COR.
d-1/2" I.R. AS PER
1/31/83 SURVEY

Found H.R.C. 5/8" I.R.
AS PER H.R.C. 79005 SURVEY
44 South & 1° 22' East

Walking to H.R.C. it was
concluded that the said
5/8" I.R. is in error =

Average Centerline of Existing Improved Road -

- 1) Currently serves all parcels shown to Irrigation Ditch.
- 2) In past there was a bridge across the Irrigation Ditch and this was the primary route to Bald Butte and Elm Mountain area Easterly of here. This road past the bridge received little use after Forest Service Road N107 was constructed.
- 3) In talking to Richard Arnold, County Surveyor, it was found that H.R.C. has RESEARCHED status of road and can find nothing in Road Records on, other than some general references to the Bald Butte Road.
- 4) Tree Growth on the immediate North and South sides of the existing road indicates that the road has shifted very little over the past 50+ years -
- 5) A strong possibility exists that this is a Public Road -

88002