


N.W. CORNER
SECTION 8
FOUND 1 1/2" IRON PIPE
& BRASS CAP H.R.C.
CORNER CARD NO. 323



5.00' 31' 37" E
2635.55'

W. 1/4 CORNER
SECTION 8
ROUND 1/2" IRON PIPE W/ 1/2"
IRON PIPE R.P.'S PIPES
BEAR NORTH, 33.00' &
WEST 33.00' SET BY
HENRY HACKETT APRIL
1910.
FOUND AXLE & BRASS CAP
S. 88° E, 5.80' SET
BY HOOD RIVER COUNTY
IN 1970 H.R.C.
CORNER CARD NO. 449



ASSUMED BASIS OF BEARING
DRAWN BY: L.H. Daley
SCALE 1" = 400'

NARRATIVE

THIS SURVEY WAS PERFORMED AT THE REQUEST OF THE
H.R.C. FORESTRY DEPT. IN ORDER TO LOCATE A PROPERTY
CORNER AND PROPERTY LINE BETWEEN SECTIONS 7 & 8 T.2N, R.10E,
AND ALSO TO CHECK ON A POSSIBLE TIMBER TRESPASSE. THE
N.W. & S.W. CORNERS OF SECTION 8 WERE FOUND & ACCEPTED. THE 1/4
CORNER BETWEEN 7 & 8 HAD BEEN MOVEMENTED IN 1970 BY
H.R.C. AN AXLE WAS FOUND AT THAT TIME AND A 2" I.P. WAS
DRIVEN OVER THE AXLE & BRASS CAP SET IN SAID PIPE.
I HAVE BEEN UNABLE TO DETERMINE THE ORIGIN OF SAID
AXLE, AND UPON RESEARCHING THE FIELD NOTES OF A SURVEY
DONE BY HENRY HACKETT IN 1910, I DISCOVERED A 1/2" I.P. &
2 1/2" I.P.'S 33' NORTH & 33' WEST. (SEE L.H. BK. NO. 15-0-18, 63,
AND BK. 25-A 18. 2 FOR HISTORY OF THIS CORNER.) I ACCEPTED
THE 1/2" I.P. AS BEING THE CORRECT CORNER.

THE PROPERTY OWNER TO THE EAST OF THE COUNTY HAD
A CLEARCUT LOGGED IN 1984, AND TRESPASSED ONTO
COUNTY PROPERTY IN THE N.E. 1/4 OF THE S.E. 1/4 OF SEC. 7.

FILED


Dec 1988
DATE
NOV. 1988
DATE OF SURVEY
88078
DRAWING NO.
Richard G. Arnold
COUNTY SURVEYOR

Richard G. Arnold
COUNTY SURVEYOR

1/10 CORNER
CALC. POSITION

5.00' 22' 36" E
1325.01'

S.W. CORNER
SECTION 8
FOUND 1 1/2" IRON PIPE
W/ BRASS CAP H.R.C.
CORNER CARD NO. 640



HOOD RIVER COUNTY
SURVEY
T.2N, R.10E, W.M. SECTION 8