

1/16th Corner

Set 1/2" IR.

Found 1/2" IR as per DLC  
12/14/79 Survey of S.02E. 6.9'

Note: sold IR was based upon  
incorrect 1/4 Corner of Sec.10  
and Sec.11.

1/16th Corner  
The NE corner of the  
SE 1/4 of the NE 1/4  
of Section 10.

1315.73'  
1275.73'  
N 89°37'30" E

Tax Lot 4200

214.50'  
Deed/Meas

Found 1/2" IR

1315.46'  
1275.46'  
N 89°37'29" E

Found 1/2" IR

Bk.37, pg.104  
Deed/Meas  
214.50'

See DLC 6/7/89 Survey.

1312.90'  
1098.40'  
N 01°14'30" E

N 01°18'55" E  
1100.66'  
1315.16'

1/16th  
Corner

1313.98'  
N 89°43'16" E

10  
11  
1/4 Corner  
Brass Cap

**FILED**

DEC 22, 1993

*Rick G. Andrus*  
COUNTY SURVEYOR

DEPUTY

Basis of bearing and Section  
control as per DLC 6/7/89  
survey.

NOTE: Iron rod (IR) monuments  
set have yellow, plastic cap  
stamped "LS 1028" affixed.

NARRATIVE: The purpose of this  
survey was to locate T.L. 4200  
of 2N 10 10A as shown.

"SURVEY"

FOR — August Piltz

LOCATION — Parcel located in the  
Southeast 1/4 of the Northeast 1/4  
of Section 10, Township 2 North,  
Range 10 East, Willamette Meridian —  
HOOD RIVER COUNTY, OREGON

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Danny L. Cron*

OREGON  
AUGUST 22, 1975  
DANNY L. CRON  
1028

Nov. 30, 1993

DLC SURVEYING  
ESTABLISHED 1976



Dan Cron  
5684 Trout Creek Road  
Pendleton, Oregon 97041  
(503) 552-0674

PILT2993.cdf  
PILT2993.dwg

November 30, 1993

SCALE 1"=200'

# 93098