

34 ● 35
1/4 Corner


●
C 1/4 Corner
Section 35
Calculated as
per DLC

Basis of Bearing and Section survey control
as per DLC CS #89040 and DLC CS #89042.

NOTE: Iron rod (IR) monuments set have yellow,
plastic cap stamped "LS 1028" affixed.

NARRATIVE: The purpose of this survey was to
locate the desired "Lot Line Adjustment" affecting
existing Tax Lots 1906 and 1907 of 2N 10 35,
as shown.

GRAPHIC SCALE



FILED

MAY 19, 1994
Richard G. Arnold
COUNTY SURVEYOR

"SURVEY"

FOR — Bob Hanel
LOCATION — Desired Lot Line Adjustment
located in the South 1/2 of the Northwest
1/4 of Section 35, Township 2 North, Range
10 East, Willamette Meridian —
HOOD RIVER COUNTY, OREGON

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron
OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

March 29, 1994



Dan Cron
5694 Trout Creek Road
Parkdale, Oregon 97041
(503) 352-6574

HANEL394.dwg
HANEL394.cdf

94050

March 29, 1994