
## BOUNDARY LINE ADJUSTMENT IN THE E 1/2, SEC 10, T 2 N, R 10 E, WM COUNTY OF HOOD RIVER, STATE OF OREGON



SURVEY AND FOUND THAT THE EXISTING EAST 1/4 CORNER OF THE SECTION WAS INCORRECT AND

BASED ON THE 1981 SURVEY.

FOUND THE CORRECT CORNER. THE MOUNUMENTS THAT ARE SHOWN ON THE PLAT WERE RECALCULATED

Hood River, Oregon 97031

Tele: (503)386-3322

DATE: JANUARY 21, 1998

JOB NO.: 98002