
SURVEY OF BOUNDARY LINE ADJUSTMENT IN SECTION 20 & 29, T.2N, R.11E, WM

COLUMBIA NORTHWEST



I. RT 22" DF: NOO°E 47.87 RT 13" PINE: N44E 40.22'

RT 22 DF: SI2°E 30.29

RT 10" DF: S29W 10.18'

T-POST EAST I.O'

T-POST WEST I.O'

2. RT 16" DF: N79°W 17.17'

RT 18" DF: S51°W 17.58'

RT 9" DF: S73°E 31.96'

3. RT 16" DF: S67°W 17.98' RT18 DF: S38°W 24.72'

RT 9" DF: S54E 37.10' T-POST EAST 1.0'

4. RT 26" DF: S45°W 31.26 RT 28" DF: S9° E 36.70' 1/2" REBAR S4°E 4.27'

T-POST WEST I.O'

BT 40" PINE: NITOW, 91.74' TO SIDE CENTER NAIL (BDC TAG)

BT 47" PINE: S31°E, 71.04' TO SIDE CENTER NAIL (BDC TAG)

(FACE 8" DEEP, NO SCRIBE VISIBLE) (S30°E 106 LKS, GLO)

(SCRIBE VISIBLE, 10" DEEP) (N25°W 140 LKS, GLO)

RT 18" FIR: SII°E, 42.78' TO FACE OF USFS TAG

GRAPHIC SCALE

500

RT 9" PINE: N73°E, 27.09' TO NAIL

RT 12" FIR: S54°W, 30.15' TO NAIL

LEGAL DESCRIPTION

Boundary line adjustment deeds: Columbia Northwest Enterprises L.L.C. to Dodd deed AFN 994051 Dodd to Columbia Northwest Enterprises L.L.C. deed AFN 994050

BASIS OF BEARING

East half of north section line of Section 29, as per Reference I

REFERENCES

- 1. Hood River County Survey, Roll II Film 093, July 1978, Job No. 13-77.
- 2. Cron Survey, Section 29, T2N, RIIE, July 15, 1980.

SURVEY NARRATIVE

Control for this survey was established using an Ashtech GG-Surveyor GPS+Glonass Surveying System, which meets the U.S. Dept. of Defense accuracy standards. Horizontal Real-Time position accuracy is I cm (.02'). From this control existing monuments were tied using a 3 second total station and related equipment. A closed loop traverse as created, whose accuracy exceeded I:10000. Least squares was used to balance the traverse to bring about mathematical closure.




TRAVERSE STATEMENT

The purpose of this survey was to prepare a boundary line adjustment along the north line of the NW 1/4 NE 1/4 Section 29 and the south line of the SW 1/4 SE 1/4 of Section 20. County brass caps were found and held at the NE section corner, the NI/4, and the SI/4, all in Section 29.

BOUNDARY LINE ADJUSTMENT

DETAIL NTS

COLUMBIA NORTHWEST



REGISTERED 9/22/99

SURVEYOR

PROFESSIONAL

OHL:

RICHARD J. LANG

LEGEND

FOUND ORIGINAL SECTION CORNER

FOUND ORIGIONAL 1/4 SECTION CORNER

MARKER FOUND AS NOTED

() PLAT OR DEED CALL

SET RED PLASTIC CAP (STAMPED R.L. SURVEY L.S. 2401) ON 5/8" X 30" REBAR

RT CORNER REFERENCE TREE WITH BELL DESIGN TAG AND NAIL SET IN SIDE OF BASE OF TREE UNLESS

NOTED OTHERWISE

BT ORIGINAL GLO BEARING TREE

Bell Design Co. makes no warranty as to matters of unwritten title such as adverse possesion, estoppel, aquiescence, etc. or to environmental concerns such as hazardous waste, pollution, wet land delineation, riparian changes, flood zones, etc.

Auditor's Certificate

Filed for record this ______ day of _____ 1999 at ____ in Book ___ of Surveys at page ____ at the request of Bell Design Co.


County Auditor

Date

Surveyor's Certificate

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Survey Recording Act at the request of Bob Demers.





HELD 3"

COUNTY BRASS CAP

SET ON 2" IRON PIPE

AS 51/4

LCR 840

29

32

FOUND 1/2" REBAR

1.67' WEST FROM N-S

CENTER SECTION LINE.

50°28'09"W 2621.12'

(2621.28' REF 2)

FROM NI/4.

4

0 00

DATE DESCRIPTION BY
8/99 DRAFTING MSH
8/99 CHECK RWB

REFERENCE POINTS:

COL. NW/DODD BLA SURVEY

1500

1"=500"

1000

FOR BOB DEMERS

HOOD RIVER COUNTY, OREGON

L:\1999\99b078\99B078.pro