SECTION CORNER FOUND 1-1/2" PIPE WITH 36 🛚 31 2" ALUMINUM CAP "2319" 30" FIR S84°W AT 31.5' HEALED BLAZE 24" FIR S 52°E AT 13.5" HEALED BLAZE SEE CORNER NO. 89 NEW REFERENCES 20" FIR STUMP N70° W AT 31.52' - 6" SPIKE AND LOCATION TAG IN TOP OF STUMP 24" FIR STUMP N2°W AT 41.67' - 6" SPIKE AND LOCATION TAG IN 5 FOUND 5/8" REBAR WITH TOP OF STUMP STEEL FENCE POST YELLOW PLASTIC CAP "GILBERTSON LS 2047" SOUTH AT 1.0' SEE CS 92103 REBAR IS S 0°58'15" E AT 1,342.88' FROM NE CORNER AND 1.66' WEST OF LINE LONGVIEW TIMBER 1/4 CORNER FOUND BLM 3-1/4" BRASS CAP DATED 2002 SEE BLM SURVEY DATED -213 FOUND STEEL FENCE POST 21.5 SOUTH -91' AND 4' WEST OF FIBER GLASS ROD JUNE 18, 2003, GROUP NO. 2019, OREGON SEE CS-80040 FOUND STEEL FENCE POST 2' WEST OF LINE FOUND STEEL FENCE POST 2' WEST OF LINE LONGVIEW S 1/16 CORNER TIMBER FOUND RAILROAD SPIKE IN PAVEMENT, SEE CS-80040 STEEL FENCE POST SET ON LINE STEEL FENCE POST SET ON LINE - 145' - 68' → 36 1 31 - 133' STANDARD SECTION CORNER FOUND U.S. GENERAL LAND OFFICE 3-1/2" BRASS MONUMENT DATED 1940 REFERENCES FOUND AS NOTED BY BLM SURVEY DATED JUNE 18, 2003

GROUP NO. 2019, OREGON

BEARINGS BASED ON SURVEY CS-80040 FROM THE EAST 1/4 CORNER TO THE SOUTHEAST SECTION CORNER



LEGEND

SECTION CORNER, 1/4 CORNER
FOUND AS NOTED

MONUMENT FOUND AS NOTED

STEEL FENCE POST FOUND AS NOTED

1/2"x 6' FIBER GLASS ROD SET ON LINE

STEEL FENCE POST SET ON LINE

() RECORD BEARING AND/OR DISTANCE

LINE MARKED WITH 1/2"x 6' FIBER GLASS RODS SET ON LINE, BLUE AND PINK FLAGGING BETWEEN RODS, TREES ALONG LINE PAINTED WITH BLUE PAINT.

NOTE: REFERENCES HAVE YELLOW LOCATION TAG AND 6"INCH SPIKE IN TOP OF STUMP BEARING TO REFERENCE TAKEN WITH HAND COMPASS, DISTANCES MEASURED TO SPIKE. RECORD OF SURVEY
FOR
LONGVIEW TIMBER
IN THE NE 1/4 AND IN THE SE 1/4 OF
SECTION 36, TIN, R9E, W.M.
HOOD RIVER COUNTY, OREGON

LINES MARKED AUGUST 30 & 31, 2011

NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO LOCATE THE EAST PROPERTY BOUNDARY OF LONGVIEW TIMBER DESCRIBED IN DEED NUMBER 2007-02460 PARCEL 43: THE EAST HALF OF SECTION 36

THE NORTHEAST SECTION CORNER, EAST 1/4 CORNER, SOUTH 1/16 CORNER AND SOUTHEAST SECTION CORNER WERE FOUND AS NOTED AND HELD TO ESTABLISH LINE THE NORTH 1/16 CORNER SET IN CS-92103 WAS NOT ACCEPTED IN THIS SURVEY.

A TRAVERSE WAS RUN FROM THE NORTHEAST CORNER TO EAST 1/4 CORNER, TO THE SOUTHEAST CORNER. THE PROPERTY LINES WERE THEN RUN, TRAVERSE LOOPS CLOSED AND ADJUSTED. SURVEY WAS DONE WITH A TOPCON GTS-2.

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION AT THE REQUEST OF LONGVIEW TIMBER CORP. IN JUNE 2011.

GEORGE J. FORD, PLS CERTIFICATE NO. 2210

PO BOX 353 KLICKITAT, WA 98628 (509) 369-1014

