N.1/4 COR. SEC.5

Position as per Bishop 2/20/78 Survey - Original evidence is at corner -

W 1/4 COR. SEC.5

Set nail & stake -
Found the following as per J.L.H. March 1909 Survey -
1.) Creek 169.29' South @ 13.2' West -
2.) Remains of 36" fir bearing East - 72.60' -
3.) Remains of a 36" fir bearing East - 324.06' -
4.) Remains of a 30" fir bearing N.21° W. - 34.32' -

E.1/4 COR. SEC.5

Found - 5/8" I.R. as per Bishop 2/20/78 Survey - Original evidence is at corner -



S.W. COR. SEC.5

Found - Brass Cap as per Bishop 2/20/78 Survey - Original evidence is at corner -

S.1/4 COR. SEC.5

Set nail & stake -
Found remains of down ancient fence intersection to the South, East, & West - This intersection is assumed to be the fence corner at the S.1/4 corner as described in J.L.H. March 1909 survey -

S.E. COR. SEC.5

Position as per Bishop 2/20/78 Survey - Original evidence is at corner -

FILED
OCT 12 1984
Richard J. Arnold
COUNTY SURVEYOR
DEPUTY

REGISTERED PROFESSIONAL LAND SURVEYOR
Danny L. Cron
OREGON AUGUST 22, 1975
DANNY L. CRON
1028

Oct. 1, 1984
Revised 10/26/84 to show the North 38' of the S.E.1/4 of the S.W.1/4 of Sec. 5 -

"J.L.H." refers to John Leland Henderson Mar. 1909 survey of Sec. 5 as performed by W.T. Eddy -

"SURVEY"

FOR - Palladean Land Company & James & Barbara Lago -

LOCATION - The N.E.1/4 of the S.W.1/4 of Sec. 5, T. 2 N., R. 10 E., W.M. -

HOOD RIVER COUNTY, OREGON -

Scale - 1" = 1000'

Basis of Bearing & Partial Section Control as per Bishop 2/20/78 Survey -

NOTE - Iron rod (I.R.) monuments set have yellow, plastic cap stamped "LS 1028" affixed -

D.L.C. Surveying
Dan Cron
5694 Trout Creek Rd.
Parkdale, Ore. 97041

#84060