


SECTION OR SUBDIVISION

1/4 - 13 | 18

TWP. 1N, RANGE 10411 E, W.M.CORNER No. 232-A

CORNER DESCRIPTION

Set 1 1/2" I.P.W/AWM cap.
 Found 1 Original BT
 30" DF 41.6' S 88° W - Scribed
 " 1/4". 1 Poss. Original
 stump badly Rotted S 14° E
 36.3' - No visible scrib-
 ing. Note: We set new
 corner from one good
 BT - Stump didn't Fit.
 HRC May 1980
 OVER →

W.O. REF. CALC. POSITION 8/91CARD 7OF 7

FD. 8x5 x 10 ROCK MARKED "1/4" 8' DOWN HILL OF "AN"
EXISTING 1" PIPE. S 14° E 12 1/2' FRM NEW COR.

232-A