

SECTION OR SUBDIVISION

1/4 S27/S26

CORNER No.

544

TWP.

2N

RANGE


10

E

W.M.

CORNER DESCRIPTION

11-22-89



W.O. REF.

CS BK #1-89

RESEARCH & TIES BY HRC
& DLC SURVEYING PROVED THE
ED. B.L. TO BE IN ERROR AND
HRC MONUMENTED THE CALCULATED
POSITION AS PER J.L.H. 1910±.
FILLED OLD MON BOX; SET
NEW MON BOX @ W EDGE PAVEMENT.

CARD

1

OF

1

