

SECTION OR SUBDIVISION

1 6
12 7

CORNER No.

596

TWP... 2 N., RANGE... 10 E., W.M.

CORNER DESCRIPTION

R 10 E

R 11 E

SEC. COR

DRIVE

TO EAST
SIDE GRADE

POLE
W/TAG

N 88 W
17 15

DRIVE

31 1/4
16 1/2

CORNER
PEAR TREE

ED. BRASS CAP IN

PRIVATE DRIVE

TAGGED UTILITY POLE

11-2-72 H.R. Co.

BRASS CAP SET BY

NEWTON SURVEYING

CO. 4/25/78

W.O. REF.

#1035-PG 72 N.S. Co.

CARD

1

OF

2

over

Ceta crew set 2 $5/8"$ relay
bar references

S 45° W 40.70'

S 45° E 30.75'

1978

(596)

GLO stone(broken) found in 1912 by Murray Kay, and replaced with a galvanized pipe.
Corner remonumented in 1972 by private surveyor with pipe and brass cap.