


SECTION OR SUBDIVISION 22 S/4

CORNER No. 33

TWP. 2N, RANGE 10 E, W.M.

CORNER DESCRIPTION



S/4 Corner Iron Pin
under pavement Inter-
section W. east Drive &
Summit Rd.

SEE NEXT

CARD

33-A

W.O. REF. _____

CARD 1 OF 2

SECTION OR SUBDIVISION


22-27 1/4

CORNER No.

33-A

TWP. 2N, RANGE 10 E, W.M.

CORNER DESCRIPTION

1/4 CORNER $\frac{22}{27}$

T2N R10E,

1/2 IRON ROD FD,

3" UNDER PAVEMENT,

(T.E.C.) 12-28-70

SET BRASS CAP IN

MONUMENT CASE JULY 1971

RAISED MON BOX 9/90; NEW R.P.S'

W.O. REF. SEE TENNESON MAP

CARD 2 OF 2

FOR PHILLIPS #4184