


SECTION OR SUBDIVISION

TWP. 15, RANGE 10 E, W.M.



W.O. REF. _____

CORNER No. 197

CORNER DESCRIPTION

ROCK $\begin{matrix} \equiv \\ \equiv \\ \equiv \\ \equiv \\ \equiv \end{matrix}$ $\begin{matrix} \equiv \\ \equiv \\ \equiv \end{matrix}$
S E

P. PINE 32" S 72° W 150'
COR IS UNDER DRIFT
FENCE S. OF RIDGE
4-30-45 V.B.E.

This cor reset
by BLM in 1985
rock is incorrect
RJA

CARD _____ OF _____