


SECTION OR SUBDIVISION

TWP. 2.N., RANGE 11 E, W.M.

30	29
31	32



~~W.O. REF.~~ VIST'D BY H.R. CO. CETA  
 CREW (L.S.), 3-78

CORNER No. 340

CORNER DESCRIPTION

FD. 1 1/2" I.P. w/ BRASS CAP  
 4" ABOVE GROUND UNDER  
 FENCE LINE (WHICH RUNS <sup>W E</sup> 54 1/2'  
 FROM COR.) FD. 4 OLD B.T.S:  
 40" PINE N76W, 59', DOWN E  
 ROTTING  
 8" OAK N87E, 13.5', BLAZED  
 5" OAK N22E, 5', BLAZED  
 6" OAK N42W, 4.5', BLAZED  
 w/TAG  
 FD. 3 MORE RECENT (OVER)

CARD 2 OF 2

B.T.S: 12" FIR N65W, 12', SCRIBED "SC"

(340)

22" FIR N43E, 39', SCRIBING (ON BUTT) IS ILLEGIBLE

8" FIR S33E, 23', SCRIBED "SC"

FD. REF. TAG ON 30" FIR STUMP ON W. SIDE OF FIR MT. RD.,  
1050' W. OF COR. ESTABLISHED A MORE VISIBLE REF. ON  
8" PINE ON E. SIDE OF RD. W/ X BLAZED AND TAG  
ON E. FACE, FROM WHICH COR IS E., 1000'.

---

Fd orig pine B.T. (now in office)

cor is in correct location - RJA.

1979