


SECTION OR SUBDIVISION

5/4  
8/9

CORNER No. 368

TWP. 1 N., RANGE 11 E., W.M.

CORNER DESCRIPTION



FD. REBAR AS COR 12" ABOVE  
 GROUND, DIRECTLY BENEATH FD.  
 3'x2" I.P. REPLACED W/2"  
 I.P. AND BRASS CAP. ALSO FD.  
 4 B.T.S., ALL W/TAGS, NO BLAZES:  
 8" FIR N77E, 14.8'  
 28" FIR S45W, 24.4'  
 32" FIR N62W, 29.5'  
 6" FIR N5E, 38.0'  
 COR. REF'D TO 2 1/2" PINE ON W.  
 SIDE OF HUSKY RD. FROM (OVER)

W.O. REF. \_\_\_\_\_

CARD 2 OF 2

WHICH IT IS S., 409. 4-78, HRC-LS

SECTION OR SUBDIVISION

Sec Cor.

$\frac{5}{8}$ /  
 $\frac{1}{9}$

CORNER No.

663

TWP. 1 N, RANGE 11 E, W.M.

24" Doug. Fir

6" WHITE  
FIR



N  
29  
62°  
W

N 5  
38  
W

N 77° E  
14  
8" Doug.  
FIR

S 45° W  
24

24" Doug.  
FIR

W.O. REF.

CORNER DESCRIPTION

3" I.P. WITH  $\frac{5}{8}$ " REBAR  
WITH PLASTIC CAP  
DRIVEN INTO CENTER  
OF PIPE. 4/75

CARD OF

SECTION OR SUBDIVISION

Sec Cor.

$\frac{5}{8}$ /  
 $\frac{4}{9}$

CORNER No.

663

TWP. 1 N, RANGE 11 E, W.M.

24" Doug. Fir

6" WHITE FIR

8" Doug. Fir

24" Doug. Fir

W.O. REF.

CORNER DESCRIPTION

3" I.P. WITH  $\frac{5}{8}$ " REBAR  
WITH PLASTIC CAP  
DRIVEN INTO CENTER  
OF PIPE. 4/75

CARD

OF