


SECTION OR SUBDIVISION SEC. 7
NW SEC. COR.

TWP. 2N, RANGE 8E, W.M.



W.O. REF. _____

CORNER No. 636

CORNER DESCRIPTION

BRASS CAP SET
IN CONCRETE APPROX.
60' N OF AIRPORT
RUNWAY. 6-73 HRCO.

CARD _____ OF _____

HOOD RIVER COUNTY

T 2N . R 8E , W.M.

Corner Code No. CC0636

Segregated Surveys:

Name N.W. corner Section 7 Corner No. _____
(DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite)

1. History of Corner Establishment and Subsequent Restoration:

Section corner was found in 1973 by Hood River County Survey Department and remonumented same year.

2. Description of Evidence Found:

1" iron pipe was found, tag on fence pole also found.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location, Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. _____ Page No. _____ Date of work _____.

Section Corner is brass cap set in concrete monument.
R.P. #1 is brass cap set in concrete monument, bears south 20 feet
Fence post with tag bears N 29° W 20.7 feet.

Oregon Plane Coordinates: North Zone, X 1,647,256.471 Y, 735,797.41

Second Order Accuracy. Derived from: _____,

Pin Pointed on Photo No. _____ Date _____ Located at _____

Note: X - easting
Y - northing

CC0636

Brass cap set in concrete approximately 60 feet north of Airport runway

DESCRIPTION OF SURVEY STATION

STATE OREGON

COUNTY HOOD RIVER

NAME OF STATION NW Cor. Sec. 7 T2N, R8EWM

JOB NO. 18-75

CHIEF OF PARTY David Downing FIELD NOTES same DATE 11-18-75

STATION MARK	SURVEY POINTS AND PROMINENT OBJECTS WHICH CAN BE SEEN FROM GROUND STATION	DISTANCE	BEARING
C-F	Railroad spike with punch mark NOTE: All bearings and distances are Oregon State Plane Coordinates, North Zone	1,710.07	S83°44'04"E

