

SECTION OR SUBDIVISION

34 E 1/4


CORNER No.

9016

TWP. 3N, RANGE 10 E, W.M.

CORNER DESCRIPTION

round metal
water box



corner not found
but both R.P.'s
were found. R.P.'s
were set while
orig. stone was
in place

RJA 1981

set 1/2" I.P. w/ brass cap
1983 RJA.

W.O. REF.

CARD

OF