

April 15, 2002

Sal D'Auria 125 Castle Court Lafayette, California 94549

Subject: Location of property corner monument of your property in Hood River County, Oregon.

Dear Mr D'Auria:

As per your request, on Friday, April 12, 2002, I checked the location of the Survey Monument that I had previously set at the Southwest corner of your property as it abuts Smullen Road. I also checked the iron pipe at the corner directly East.

I am also aware that you had the firm of Tenneson Engineering mark the line between the two above-mentioned corners and they had found the Southwest corner to be 65 feet North of were they though it should be.

I was able to find the original survey control that I set during the survey that I preformed for the Jacobson's. Using this information I reset the Southwest corner. It landed within two inches of the temp corner that Tenneson set and 65 feet South of a 5/8" iron rod with a yellow plastic cap, which the cap has been mushroomed over and the letters on it are not legible. It appears that iron rod found is not at the original location as set by our firm and it appears that it has been moved. My Party Chief showed me some bush cuttings that are South of the location of the found iron rod which he remembers cutting while setting the corner.

If any further assistance is required please feel free to contact me.

Yours truly,

Anthony C. Klein PLS

Cc: John and Brady Jacobson

Cc: Randy Johnson, Hood River County Survey