


RESUME'

ALL CALCULATIONS BASED ON COORDINATES AS ESTABLISHED BY TENNESSEN ENG. CORP. (T.E.C.) 1968 SURVEY, W.O. #3737. AT THAT TIME T.E.C. DID NOT ACCURATELY TIE TO THE CORNERS ALONG THE SOUTH LINE OF SEC. 33 & 34 WHICH WERE ESTABLISHED BY A 1940 G.L.O. DEPENDENT RESURVEY. THE COORDINATES USED BY T.E.C. FOR THE SOUTH LINE WERE ESTABLISHED BY A B.P.A. SURVEY AND SHOWN ON "JOHN DAY-KEELER NO. 1" (PARKDALE-SANDY SEC) DRAWINGS. SOME DISCREPANCY WAS FOUND BETWEEN OUR FOUND COORDINATES & T.E.C. COORDINATES. IT WAS DECIDED TO HOLD T.E.C.'S COORDINATES BECAUSE OF THE EXTRUSIVE WORK DONE TO THE NORTH OF THESE CORNERS. THE SW CORNER OF 33, SW CORNER OF 34, & THE SW OF 34 WERE TIED AND THE CORRECTED DISTANCES SHOWN.



CREW:
DAVE DOWLING - PARTY CHIEF
ANTHONY KLEIN - PARTY CHIEF
RICHARD ARNOLD - INSTRUMENTMAN
LYNN LESSLEYOUNG - CHAINMAN

DATE SURVEYED:
JUNE, JULY, AUG., 1976

7658

HOOD RIVER COUNTY SURVEY OFFICE	
SURVEY FOR HOOD RIVER COUNTY FORESTRY DEPT	
IN	
SEC 26 1/4 T. IN. R. 9 E. W.M.	

FILED
NOV 9 1976
Ronald J. Merry
COUNTY SURVEYOR
By _____
DEPUTY

DATE: OCT 25, '76	JOB NO. 13-75
SCALE: 1" = 100'	FILE NO. _____
DRAWING ACK	SHEET 1 OF 1

CHART-PAK, INC. LEEDS, MASS. SPH 3677

#7658

6-128