

11-038

#28083

W 1/4 COR.
SEC. 8
SEE H.R.C. 6/73
SURVEY

1325.62

1320.00

2.00° 25' 39" E

N. 89° 25' 56" W.

1320.00

S.W. COR.
SEC. 8
Fd.-B.C. as per
H.R.C. 6/73 SURVEY

1315.89

C 1/4 COR.
SEC. 8
SEE H.R.C. 6/73
SURVEY

1325.62

670.0

N. 89° 22' 11" W.

260.0

5.00' 38" 20" C.J.

260.0

100' 13"

2.00° 38' 20" E

1315.89

N. 89° 22' 11" W.

S. 1/4 COR.
SEC. 8
Fd.-B.C. as per
H.R.C. 6/73 SURVEY

N. 89° 22' 11" W.

2652.84

3959.30

2431.78

268.0

S. 0° 18' 14" W.

200.0

30'

25'

33.73

30'

25'

200.0

30'

25'

33.73

30'

25'

200.0

30'

25'

33.73

E 1/4 COR.
SEC. 8
Fd.-B.C. as per
H.R.C. 6/73
SURVEY

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron
OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

JUNE 21, 1978

scale - 1" = 600'

Basis of Bearing & section
subdivision as per H.R.C.
survey of Sec. 8 dated
6/4/73

• = 1/2" iron rod monument
set unless noted

" SURVEY "

FOR - Thomas Manfall

LOCATION - Parcel located

in the S. 1/4 of SEC. 8,

T. 2N, R. 10E., W.M.

HOOD RIVER COUNTY,

OREGON

FILED

JUL 12 1978

Frank J. Miller

COUNTY SURVEYOR

8x 1000 ft

DEPUTY

78083