



NOTE: Current assessment's map shows this line as East/West, however this cannot be. The following elements control a deed, listed in order of importance:

- 1) DEED OBJECTS
- 2) DISTANCES
- 3) BEARINGS
- 4) AREA

NOTE: L.A.H. 5/22/1971 shows lands belonging to Jos. E. Hall, Jr. whereby said L.A.H. also shows this Road, even though said map has a drafting error as to the location of Binns Hill Road.

Scale - 1" = 100'

Assumed Basis of Bearing -

NOTE: Iron rod (IR) monuments set have yellow, plastic cap stamped '25 1028' affixed.

NARRATIVE: The Purpose of this survey was to locate existing deed lines as shown. This survey will not agree with Gaylord T/83 survey in that he never found the true 1/4 corner at 17.

REGISTERED PROFESSIONAL LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

July 22, 1988

F I L L E D

SEP 13, 1988
Richard G. Arnold
COUNTY SURVEYOR

DEPUTY