


NARRATIVE

THIS SURVEY WAS PERFORMED AT THE REQUEST OF THE HOOD RIVER COUNTY FORESTRY DEPARTMENT IN ORDER TO LOCATE THE S.E. 1/16TH CORNER OF SECTION 19, T.1S., R.10E., W.M. WE TIED TWO IRON RODS THAT WERE SET BY DLC SURVEYING IN 1982 (COUNTY SURVEY NO. 82036) WE THEN CALCULATED AND SET THE S.E. 1/16, USING A SECTION BREAKDOWN DONE IN 1983 BY THE HOOD RIVER COUNTY SURVEY DEPARTMENT (COUNTY SURVEY NO. 83045). THIS 1983 SURVEY USED A DIFFERENT POSITION FOR THE WEST 1/4 CORNER THAN DLC SURVEYING USED FOR HIS (COUNTY SURVEY NO. 82036) SURVEY. THIS RESULTED IN A SHIFT IN POSITION OF DLC SURVEYING IRON ROD OF ABOUT 1.5 FEET. WE MOVED SAID IRON ROD TO THE CORRECT POSITION.



SCALE 1" = 300

BASIS OF BEARING AS PER HRC SURVEY
DATED NOVEMBER 28, 1983 HRC DRAWING
NO. 83045

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard J. Arnold
OREGON
JULY 15, 1983
RICHARD J. ARNOLD
2038

Sept. 1992

FILED

Richard J. Arnold
COUNTY SURVEYOR

HOOD RIVER COUNTY
SURVEY
T.1S., R.10E., W.M. SECTION 19
HOOD RIVER, OREGON