

1/16th Corner
 The NW corner of the SE 1/4 of the SE 1/4 of Section 36 - Found DLC 1/2" IR

1/16th Corner
 The NE corner of the SE 1/4 of the SE 1/4 of Section 36 - Set 1/2" IR

1/4 Corner
 Calculated position as per DLC C.S. 85015 - NOTE: HRC C.S. 83048 position is 3.55' N. and 4.4' E.

1/16th Corner
 The SW corner of the SE 1/4 of the SE 1/4 of Section 36 - Calculated as per DLC C.S. 85015

Section Corner
 Found HRC Brass Cap

Basis of Bearing and Survey control as per DLC C.S. 85015.
 NOTE: Iron rod (IR) monuments set have yellow, plastic cap stamped "LS 1028" affixed.

NARRATIVE: The purpose of this survey was to locate the corners of T.L. 4000 of 2N 10 36 as shown. Hood River County C.S. 83048 would place the Westerly line of said T.L. 4000 approximately two feet Easterly of the location staked by this survey.

"SURVEY"

FOR - McCoy Columbia Properties
 LOCATION - Parcel located in the Southeast 1/4 of the Southeast 1/4 of Section 36, Township 2 North, Range 10 East, Willamette Meridian -
HOOD RIVER COUNTY, OREGON


REGISTERED
**PROFESSIONAL
 LAND SURVEYOR**

Danny L. Cron

OREGON
 AUGUST 22, 1975
DANNY L. CRON
 10228

Jan 26, 1994

DLC SURVEYING
 ESTABLISHED 1976



Dan Cron
 5694 Trout Creek Road
 Parkdale, Oregon 97041
 (503) 352-6574

MCCOY194.dwg
 MCCOY194.cdf

SCALE 1" = 300'

Jan. 26, 1994



FILED

FEB 2, 1994
Richard J. Auer
 COUNTY CLERK

#94010